# Stauffer Creek 319 Grant (Bear Lake CD)

| | |
|---|---|
| **Program** | District Technical Assistance (ISWCC) |
| **Lead Implementer** | Idaho Soil and Water Conservation Commission |
| **Funders** | Idaho Department of Environmental Quality, Private Party |
| **Other Organizations** | Bear Lake Conservation District |
| **Project Primary Contact** | George Hitz (george.hitz@swc.idaho.gov) |
| **Project Stage** | Post-Implementation |
| **Duration** | 2017 - 2018 |

IDAHO SOIL & WATER CONSERVATION COMMISSION

**Conservation Support > District Technical Assistance (ISWCC)**

The project focused on working with 3 landowners to removed barriers for spawning/migration of Bonneville Cutthroat Trout, improved landowner irrigation methods, protected sensitive riparian areas, and improve stream crossings

This Photo shows an unnamed spring creek, east of St. Charles, Idaho (tributary to St. Charles Creek) with newly installed riparian fencing directly below an animal feeding operation
Credit: Bear Lake SWCD / Conservation Basics, llc.

## Key Accomplishments

- Engineering Designs Produced: **3**
- Landowner Site Visits: **3**
- Engineering & Technical Assistance Hours Requested: **529**
- Engineering & Technical Assistance Hours Allocated: **302**
- Engineering & Technical Assistance Hours Provided: **284**
- Engineering & Technical Assistance Value: **$19,429.78**

## Project Themes

- Agricultural Lands
- Healthy Watersheds
- Water

## Location




## Expenditures

*No expenditures provided*

## Photos

### Before

Stream crossing before BMP implementation on Stauffer Creek
Credit: Bear Lake SWCD / Conservation Basics, llc.

### During

Installation of irrigation mainline adjacent to Stauffer Creek. This irrigation system was installed to reduce flood irrigation and standing of migrating Bonneville Cutthroat Trout.
Credit: Bear Lake SWCD / Conservation Basics, llc.

### After

Two troughs installed to reduce livestock impacts to sensitive riparian area
Credit: Bear Lake SWCD / Conservation Basics, llc.

Stream crossing after BMP implementation on Stauffer Creek
Credit: Bear Lake SWCD / Conservation Basics, llc.

*Tracker tells stories at a broad-brush level. Individual project performance measures and expenditures should not be relied upon for complete and total accuracy and should be confirmed with a project's lead implementer. Project locations subject to confidentiality provisions under state and federal law specify the location of a local conservation district or USDA service center office.*

Project last updated 6/13/2019